

Inspection Photos

August 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 335385

Location Name: Benzel-66S93W /25SESW

Inspection Document #: 702800583

Garfield County, CO

SWNE Section 25 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Benzel-66S93W /25SESW
Location ID: 335385



Photo 1. Photo taken from the north of the Location shows an overview of the working pad area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800583

Inspection Photos
Location Name: Benzel-66S93W /25SESW
Location ID: 335385



8/23/22
+39.492099,-107.727171
50° NE

Photo 2. Photo taken from the southwest of the Location shows a patch of Russian knapweed, a List B Noxious Weed. Knapweed does not appear to have been treated.



8/23/22
+39.492801,-107.725789
121° SE

Photo 3. Photo taken from the northeast of the Location shows a patch of Russian knapweed, a List B Noxious Weed. Knapweed does not appear to have been treated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800583