

Inspected Facilities

Facility ID: 476593 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Well Drilling

Rig: Rig Name: Patterson 345 Pusher/Rig Manager: _____
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: _____
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: Keensburg

Comment: Well: 5-61-11B-14-23-3
Running Cement Trucks at the time of Inspection

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine Drilling Inspection</u>	petrie	08/26/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304403	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5841145