

KP KAUFFMAN COMPANY INC

MCCALLUM UNIT 182

Location # 324744



MECHANICAL INTELLIGENCE

Complete the Attachment Checklist

Pressure Chart ☐ Open ☐ OGCC

Current Bond Log ☐

System Survey ☐

Surveillance Survey ☐

Inspection Number ☐

Operator Name and Telephone ☐

Operator Name: Victoria Dzighinili

Operator Telephone: 303-825-4822

OGCC Operator Number: 48290

OGCC Facility ID Number: 1700 LINCOLN ST SITE 4550

State: CO Zip: 80203

City: DENVER

Well/Facility Number: 182

Location Section: 34 Township: 10N Range: 79W Meridian: 6PM

Test Type: ☐ SHUT-IN PRODUCTION WELL ☐ INJECTION WELL ☐ Reset Packer

Test to Maintain SI/TA status ☐ 5-year UIC ☐ Annual UIC Test

Describe Repairs or Other Well Activities

Wellbore Data at Time of Test

Injection/Producing Zone(s): Pierre B Perforated Interval: 1070'-1092' Open Hole Interval:

Tubing Casing/Annulus Test

Tubing Size: 2.375 Tubing Depth: 1022' Top Packer Depth: 1022' Multiple Packers? ☐ Yes ☒ No

Test Data

Log Date: 8/25/22 Well Fluid During Test: 51 Casing Pressure Before Test: 0 Initial Tubing Pressure: 0

Casing Pressure After Test: 670 Casing Pressure - 3 Min: 670 Casing Pressure Final Test: 670 Pressure Loss or Gain During Test: 0

Test Witnessed by State Representative? ☒ Yes ☐ No

OGCC Field Representative (Print Name): Michael Longworth

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joseph D. Boxley

Signed: [Signature] Title: Production Supervisor Date: 8-25-2022

OGCC Approval: [Signature] Title: Field Inspector Date: 8-25-22

Conditions of Approval, if any:



KP KAUFFMAN COMPANY INC
MCCALLUM UNIT 182
Location # 324744

