

# Inspection Photos and Issue Report

8/25/2022

Operator: UTAH GAS OP LTD DBA UTAH GAS

CORP - 10539

Location #322479

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322479



**Photo 1:** Stormwater erosion degradation at the access road.

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322479



**Photo 2:** Stormwater erosion degradation at the access road. Hard hat in photo for scale/reference.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322479



**Photo 3:** Stormwater erosion degradation at the access road.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322479



**Photo 4:** Stormwater erosion degradation at the access road.

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322479



**Photo 5:** Stormwater erosion degradation at the access road.