

Construction and Stormwater Inspection

August 10, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 459835

Inspection Document #: 697504126

Weld County, CO

NENW Section 8 T3N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DD08-03 /Multi
Location ID: 459835



Photo 1. Photo taken from the west entrance of location, facing South. Photo illustrates Operator has installed filter fabric around the entire perimeter of location and the mailbox along the entrance to comply with Rule 406.c.



Photo 2. Photo taken from the western location, facing South. Photo illustrates Operator is in process of stormwater repairs along the fill slope and ditch BMP.

Inspection Photos
Location Name: DD08-03 /Multi
Location ID: 459835



Photo 3. Photo taken from the southwestern location, facing East. Photo illustrates the sediment basin with repairs in need.



Photo 4. Photo taken from the stabilized outlet area of sediment basin.

Inspection Photos
Location Name: DD08-03 /Multi
Location ID: 459835



Photo 5. Photo taken from the southwestern location, facing South. Photo illustrates weeds in need of maintenance. Weeds were addressed on a follow up inspection conducted on 8/19/2022.



Photo 6. Photo taken from the southwestern location, facing East. See comments under Photo 5. Photo illustrates ditch maintenance is required.

Inspection Photos
Location Name: DD08-03 /Multi
Location ID: 459835



Photo 7. Photo taken from the southeastern location, facing North. Photo illustrates a run-on swale per Weld County requirements.



Photo 8. Photo taken from the eastern location, facing North. See comments under Photo 5.

Inspection Photos
Location Name: DD08-03 /Multi
Location ID: 459835



Photo 9. Photo taken from the northeastern location, facing East. See comments under Photo 1.



Photo 10. Photo taken from the northern location, facing South. Photo illustrates current operations.

