

# Construction and Stormwater Inspection

August 10, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 459852

Inspection Document #: 697504128

Weld County, CO

NWNE Section 8 T3N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DD08-02 /Pad  
Location ID: 459852



**Photo 1.** Photo taken from the west entrance of location, facing South. Photo illustrates Operator has installed filtrex around the entire perimeter of location and the mailbox along the entrance to comply with Rule 406.c.



**Photo 2.** Photo taken from the northwestern location, facing Northeast. Photo illustrates the sediment basin.



Inspection Photos  
Location Name: DD08-02 /Pad  
Location ID: 459852



**Photo 3.** Photo taken from the northwestern location, facing North. Photo illustrates the cattle guard VTC to be installed and the weir stormwater BMP to be installed.



**Photo 4.** Photo taken from the northeastern location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: DD08-02 /Pad  
Location ID: 459852



**Photo 5.** Photo taken from the eastern location, facing South. Photo illustrates a swale area that is directed to the sediment basin.



**Photo 6.** Photo taken from the southeastern location, facing Southeast. See comments under Photo 1.

Inspection Photos  
Location Name: DD08-02 /Pad  
Location ID: 459852



**Photo 7.** Photo taken from the southeastern location, facing West. See comments under Photo 1.



**Photo 8.** Photo taken from the southern location, facing Northwest. Photo illustrates construction and stormwater activities underway.