

# Construction and Stormwater Inspection

August 10, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 460293

Inspection Document #: 697504138

Weld County, CO

NENW Section 29 T4N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: C29-03 /Pad  
Location ID: 460293



**Photo 1.** Photo taken from the northwestern location, facing South. Photo illustrates the Operator sign on the topsoil stockpile. Topsoil has been temporarily stabilized with equipment tracking.



**Photo 2.** Photo taken from the western location, facing South. Photo illustrates filtrex has been installed around the entire perimeter of location.



Inspection Photos  
Location Name: C29-03 /Pad  
Location ID: 460293



**Photo 3.** Photo taken from the southern location, facing Southeast. See comments under Photo 2.



**Photo 4.** Photo taken from the southeastern location, facing South. See comments under Photo 2.



Inspection Photos  
Location Name: C29-03 /Pad  
Location ID: 460293



**Photo 5.** Photo taken from the southeastern location, facing Northeast. See comments under Photo 2.



**Photo 6.** Photo taken from the eastern location, facing North. See comments under Photo 3.



Inspection Photos  
Location Name: C29-03 /Pad  
Location ID: 460293



**Photo 7.** Photo taken from the northeastern location, facing West. See comments under Photo 3.



**Photo 8.** Photo taken from the northwestern location, facing West. Photo illustrates a water truck.