

Inspection Photos

August 29, 2022

Operator: Crowheart Energy LLC - #10776

Location ID: 313190

Location Name: Bakers Peak Unit-611N91W /12SWSE

Inspection Document #: 702800610

Moffat County, CO

SWSE Section 12 T11N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Bakers Peak Unit-611N91W /12SWSE

Location ID: 313190



Photo 1. Photo taken from the northwest of the Location shows the access road. The road has not been reclaimed.



Photo 2. Photo taken from the north shows an overview of the Location. The Location has not been reclaimed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800610

Inspection Photos

Location Name: Bakers Peak Unit-611N91W /12SWSE

Location ID: 313190



Photo 3. Photo taken from the south of the Location shows the pad has not been reclaimed. The pad surface is flat, compacted and graveled.



Photo 4. Photo taken from the west shows the fill slope remains. The Location has not been recontoured/regraded to match the surrounding landscape. Also note areas adjacent to the working pad/areas previously disturbed during pad construction have not been properly reclaimed and are a monoculture of cheatgrass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800610

Inspection Photos

Location Name: Bakers Peak Unit-611N91W /12SWSE

Location ID: 313190




Photo 5. Photo taken from the north of the Location shows areas adjacent to the working pad/areas previously disturbed during pad construction have not been properly reclaimed and are a monoculture of cheatgrass.



Photo 6. Photo taken from the southern edge of the working pad area. Photo shows the Location has not been recontoured; the flat pad and cut slopes are evident. Photo also shows bull thistle, a List B Noxious Weed (red circle) and a monoculture of cheatgrass, on the working pad and cut slopes.

Inspection Photos
Location Name: Bakers Peak Unit-611N91W /12SWSE
Location ID: 313190



Photo 7. Photo taken from the southwest of the working pad shows gully erosion with an active headcut and unstable sides. Photo also shows multiple bull thistle plants (dark green vegetation) and a monoculture of cheatgrass (tan vegetation).



Photo 8. Photo taken from the southwest of the working pad shows gully erosion. Photo also shows multiple bull thistle plants (red circles).

