

Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962



Photo 1 – 18-13-12 Wellhead – Stained Soil



Photo 2 – 18-7-10 Wellhead – Stained Soil



Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962



Photo 3 – 18-13-15 Wellhead – Stained Soil



Photo 4 – Separators

**Inspection Photos**  
**Location Name: Flaherty 18 PAD**  
**Location ID: 443962**



**Photo 5 – VRU**



**Photo 6 – Tank Battery**



**Inspection Photos**  
**Location Name: Flaherty 18 PAD**  
**Location ID: 443962**



**Photo 7 – Gas Meters**



**Photo 8 – ECD**

**Inspection Photos**  
**Location Name: Flaherty 18 PAD**  
**Location ID: 443962**



**Photo 9 – Sign at Entrance**