

Inspection Photos  
Location Name: Tiffany 1  
Location ID: 325498



IMG 01  
Well sign



IMG 02  
Location overview





**IMG 03**  
**Flow line**



**IMG 04**  
**Muffler hose**





**IMG 05**

**Fuel container**



**IMG 06**

**Impacted material**





**IMG 07**  
**Ruts**



**IMG 08**  
**Ruts**





**IMG 09**  
**Muffler Hose**



**IMG 10**  
**Berm height**