

Inspection Photos

Location Name: FOSS - USX AA-66N63W /5SWSW

Location #: 306382



Photo #1

Foss - USX AA 5-25 (05-123-24562) Wellsite
Temporarily Abandoned | TA



Photo #2

Foss - USX AA 5-25, 5-11 Battery site
Abandoned: ALL Equipment Removed