

Final Reclamation Inspection

August 17, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328530

Inspection Document #: 697504154

Weld County, CO

NENE Section 33 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRC #33-1M
Location ID: 328530



Photo 1. Photo taken from the associated tank battery location, facing North. Photo illustrates all equipment has been removed. Water line is not related to oil and gas activities. Operator failed to properly contour location.



Inspection Photos
Location Name: UPRC #33-1M
Location ID: 328530



Photo 2. Reference tank battery photo taken from the tank battery, facing Southwest.

Inspection Photos
Location Name: UPRC #33-1M
Location ID: 328530



Photo 3. Photo taken from the associated tank battery location, facing Northeast. Photo illustrates the well location on the other side of the access road. The adjacent area appears to be utilized for soil stockpiles.



Photo 4. Photo taken from the associated tank battery location, facing East. See comments under Photo 3.

Inspection Photos
Location Name: UPRC #33-1M
Location ID: 328530



Photo 5. Photo taken from the location, facing North. Photo illustrates the access road is being utilized by the surface owner to access a stormwater management area.



Photo 6. Photo taken from the location, facing South. See comments under Photo 5.

Inspection Photos
Location Name: UPRC #33-1M
Location ID: 328530



Photo 7. Google Earth aerial imagery from 9/29/2020 illustrates the Operator reclaimed the location and access road.

