

# Inspection Photos

August 29, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313219

Location Name: Bakers Peak-611N91W /12NWSE

Inspection Document #: 702800619

Moffat County, CO

NWSE Section 12 T11N R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313219



**Photo 1.** Photo taken from the northwest of the Location shows the access road in the foreground of the photo has been reclaimed. Photo also shows an overview of the Location (red circle). Note also, tire tracks showing vehicles accessing Location.



**Photo 2.** Photo taken from the northeast shows an overview of the Location. Note vehicle tracks throughout.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800619

## Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313219



**Photo 3.** Photo taken from the center of the Location shows gully erosion. Photo also shows patches of desirable western wheatgrass in foreground compared to cover of cheatgrass (Noxious Weed) and alyssum (annual undesirable plant species/weed) in other areas.



**Photo 4.** Photo taken from the south of the Location shows a natural drainage off-site which also runs through the Location. The sides of this drainage are well stabilized by perennial vegetation and gully erosion is not present, as it is on Location. See Photo 3.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800619

## Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313219



**Photo 5.** Photo taken from the north of the Location shows the start of the disturbed area vegetation monitoring transect.



**Photo 6.** Photo taken from the north of the Location shows the ground surface at the start of the disturbed area vegetation monitoring transect.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800619

Inspection Photos  
Location Name: Bakers Peak-611N91W /12NWSE  
Location ID: 313219



**Photo 7.** Photo taken from the center of the Location shows the end of the disturbed area vegetation monitoring transect.



**Photo 8.** Photo taken from the center of the Location shows the ground surface at the end of the disturbed area vegetation monitoring transect.



Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313219



**Photo 9.** Photo taken to the south of the Location shows the start of the reference area vegetation monitoring transect.



**Photo 10.** Photo taken to the south of the Location shows the ground surface at the start of the reference area vegetation monitoring transect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800619

Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313219



**Photo 11.** Photo taken to the south of the Location shows the end of the reference area vegetation monitoring transect.



**Photo 12.** Photo taken to the south of the Location shows the ground surface at the end of the reference area vegetation monitoring transect.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800619

Inspection Photos  
Location Name: Bakers Peak-611N91W /12NWSE  
Location ID: 313219



**Photo 13.** Photo shows reference area vegetation to the north of the Location.

