

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403121402

Date Received:
07/29/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>.General</u>		<u>sjninspections@ikavenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500077

Inspection Date: 06/15/2022 FIR Submit Date: 06/16/2022 FIR Status:

Inspected Operator Information:

Company Name: SIMCOE LLC Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325784

Location Name: MAYFIELD-MELTON GAS UNIT-N33N9W Number: 1NESE County: LA PLATA

Qtrqr: NESE Sec: 1 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129557 Longitude: -107.772415

FACILITY - API Number: 05-067- -00 Facility ID: 215375

Facility Name: MAYFIELD MELTON Number: 1

Qtrqr: NESE Sec: 1 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129557 Longitude: -107.772415

CORRECTIVE ACTIONS:

1 CA# 162738

Corrective Action: Use or remove equipment per rule 606. Date: 07/01/2022

Response: CA COMPLETED Date of Completion: 07/26/2022

Operator Comment: Removed unused equipment.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500077 has been satisfactorily completed.

2 CA# 162739

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 07/01/2022

Response: CA COMPLETED

Date of Completion: 07/26/2022

Operator Comment: Installed marker on guy line rig anchor.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500077 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 7/29/2022 10:05:45 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403121402	FIR RESOLUTION SUBMITTED
403121407	Mayfield Melton 1, CA complete photos

Total Attach: 2 Files