

Inspection Photos and Issue Report

8/30/2022

Operator: NONSUCH NATURAL GAS INC

#10163

Location #324169

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 1: Photos taken from the west end of the Location. Photos 1-2 provide an overview of the Location from north, northeast, southeast to south.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location #324169



August 30, 2022



August 30, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location #324169



Photo 3: Photos show wildlife protection devices at the two methanol tanks on the Location remain missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 4: Photos taken from the interim areas of the Location; interim areas remain predominantly bare; Location remains out of compliance with 1003 rules.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 5: Photo shows erosion degradation on the cut slopes; stormwater and erosion control BMPs remain missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 6: Continued from photo 5. Photos examples showing stormwater and erosion control BMPs to minimize erosion and degradation remains missing or insufficient at the cut slopes.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 7: Photo shows degradation due to stormwater runoff from the access road; BMPs to stabilize and properly manage runoff from the Location remains missing or insufficient, resulting in continued degradation and sediment transport. 6 foot measuring stick for reference.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 8: See comments under photo 7.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 9: See comments under photo 7.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #324169



Photo 10: See comments under photo 7.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location #324169



Photo 11: Photos examples showing Noxious weed (Houdstongue) on the Location; ongoing weed monitoring/management inadequate. Rosettes evident throughout location. Larger plants have matured with viable seeds.