

Inspection Photos and Issue Report

8/30/2022

Operator: NONSUCH NATURAL GAS INC

#10163

Location #453726

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #453726



August 30, 2022



August 30, 2022

Photo 1: Photos taken from the east end of the Location. Photos 1-2 provide an overview of the Location from south, southwest, northwest to north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #453726



August 30, 2022



August 30, 2022

Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #453726



Photo 3: Photo shows unused equipment has been removed from the Location.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #453726



Photo 4: Photo taken from the east end of the Location, facing east. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location #453726



Photo 5: Photo taken from the access road, facing east. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location #453726



Photo 6: Photo taken from the access road, facing south. Photo shows stormwater runoff from the Location has resulted in erosion degradation at the Location entrance, and the access road; required stormwater and erosion control measures pursuant to Rule 1002.f remain missing or insufficient. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location #453726



Photo 7: Photo taken from the access road. Photo shows gully erosion at access road is ~2 feet deep.

