


Inspection Photos
Location Name: SRC Kiehn Pad
Location ID: 437829



Lease road entrance sign



Production facility



Inspection Photos
Location Name: SRC Kiehn Pad
Location ID: 437829



Produced water tank placards at 100' +/-



Produced water tank placards from berm wall

Inspection Photos
Location Name: SRC Kiehn Pad
Location ID: 437829



Unused downhole equipment



Unused fence panel

Inspection Photos
Location Name: SRC Kiehn Pad
Location ID: 437829



Unused stainless tubing



Unused stainless tubing

Inspection Photos
Location Name: SRC Kiehn Pad
Location ID: 437829



Tracking pad



Tracking pad

Inspection Photos
Location Name: SRC Kiehn Pad
Location ID: 437829



Location storm water BMP's



Location and lease road storm water BMP's

Inspection Photos
Location Name: SRC Kiehn Pad
Location ID: 437829



Lease road storm water BMP's



Lease road damage