

Inspection Photos and Issue Report

8/30/2022

Operator: CAERUS PICEANCE LLC

Location #335455

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #335455



August 30, 2022



August 30, 2022

Photo 1: Photos taken from the north end of the Location. Photos provide an overview of the upper areas of the Location from south to southwest. Photo right also shows areas associated with the closed facility (arrow); are not needed for production operations.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #335455



Photo 2: Photo taken from the west end of the Location, facing south. Photo shows the lower areas of the Location where the UIC facility existed; Facility has been closed and equipment removed; areas are not longer needed for production.



Photo 3: 2016 Google earth aerial imagery. Red polygon represents approximate areas (0.75 acres) of the Location no longer needed for production, subject to 1003 reclamation requirements; equipment has been removed and facility closed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #335455



Photo 4: Photo taken from the sediment trap on the southwest end of the Location; BMP has not been maintained in proper functioning condition; photo shows gully erosion and degradation to the control.