

Inspection Photos

August 29, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313311

Location Name: Bakers Peak-611N91W /12SESW

Inspection Document #: 702800622

Moffat County, CO

SESW Section 12 T11N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bakers Peak-611N91W /12SESW
Location ID: 313311



Photo 1. Photo taken from the southwest shows an overview of the Location.



Inspection Photos
Location Name: Bakers Peak-611N91W /12SESW
Location ID: 313311



Photo 2. Photo taken from the southeast shows a pipe remains on site.



Photo 3. Photo taken from the southwest shows trash/debris associated with the Location.

Inspection Photos
Location Name: Bakers Peak-611N91W /12SESW
Location ID: 313311



Photo 4. Photo taken from the north of the Location shows Canada thistle, a CO List B Noxious Weed.



Inspection Photos

Location Name: Bakers Peak-611N91W /12SESW

Location ID: 313311



Photo 5. Photo taken from the center of the Location shows the start of the disturbed area vegetation monitoring transect.



Photo 6. Photo taken from the center of the Location shows the ground surface at the start of the disturbed area vegetation monitoring transect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800622

Inspection Photos

Location Name: Bakers Peak-611N91W /12SESW

Location ID: 313311



Photo 7. Photo taken from the center of the Location shows the end of the disturbed area vegetation monitoring transect.



Photo 8. Photo taken from the center of the Location shows the ground surface at the end of the disturbed area vegetation monitoring transect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800622

Inspection Photos

Location Name: Bakers Peak-611N91W /12SESW

Location ID: 313311



Photo 9. Photo taken to the west of the Location shows the start of the reference area vegetation monitoring transect.



Photo 10. Photo taken to the west of the Location shows the ground surface at the start of the reference area vegetation monitoring transect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800622

Inspection Photos

Location Name: Bakers Peak-611N91W /12SESW

Location ID: 313311



Photo 11. Photo taken to the west of the Location shows the end of the reference area vegetation monitoring transect.



Photo 12. Photo taken to the west of the Location shows the ground surface at the end of the reference area vegetation monitoring transect.

Inspection Number: 702800622



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources