

Inspection Photos

August 31, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313403

Location Name: Thornburg Unit-611N92W /11NWNW

Inspection Document #: 702800645

Moffat County, CO

NWNW Section 11 T11N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313403



Photo 1. Photo taken to the north of the Location shows the access road remains. Vegetation growth is absent in tire tracks where soils are compacted and bare. Vegetation is well established in the center of the road and along previously disturbed road edges.



Photo 2. Photo taken to the north of the Location shows an overview of the Location. Photo also shows vehicles are utilizing the Location access road and driving on the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800645

Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313403



Photo 3. Photo taken from the south of the Location shows an overview of the reclaimed area.



Photo 4. Photo taken from the center of the Location shows the vegetation community consists of native perennial grasses and occasional shrubs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800645

Inspection Photos
Location Name: Bakers Peak-611N91W /12NWSE
Location ID: 313403



Photo 5. Photo shows reference area vegetation to the west of the Location.

