

Inspection Photos

Location Name: Jaramillo 32-6 #12-1

Location ID: 334044



IMG 01
Well sign



IMG 02
Location overview



IMG 03
Weeds at wellhead



IMG 04
Weeds on berms



IMG 05
Weeds on berms



IMG 06
Weeds at separator



IMG 07
Weeds at separator




IMG 08
Chemical tank with no label/sign



IMG 09

Impacted material



IMG 10

Tank sign is deteriorating



IMG 11

Tank has no label/sign



IMG 12

Flow line





IMG 13
Trash



IMG 14
Trash



IMG 15
Rig anchor

IMG 16