

Location Name: Stubbs 1 pit Location ID/API #: 100862



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Stubbs 1 pit Location ID/API #: 100862



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Access road was being bladed during inspection.



Location Name: Stubbs 1 pit Location ID/API #: 100862



9/1/22 12:41  
38.40971N 102.45272W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Oil stained soil on well pad.**



Location Name: Stubbs 1 pit Location ID/API #: 100862



9/1/22 12:40  
38.40949N 102.45280W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Oil stained soil on well pad.**



Location Name: Stubbs 1 pit Location ID/API #: 100862



9/1/22 12:38  
38.40942N 102.45298W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Large vegetation kill area off west side of well pad and near  
the location of closed pit.**

Location Name: Stubbs 1 pit Location ID/API #: 100862





Location Name: Stubbs 1 pit Location ID/API #: 100862



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Large vegetation kill area off west side of well pad and near  
the location of closed pit.**