

Inspection Photos
Location Name: Southern Ute 16-6
Location ID: 312122



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Tank capacity is not labeled

IMG 04