

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2022

Submitted Date:

09/06/2022

Document Number:

707600209

**FIELD INSPECTION FORM**Loc ID 419484 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email   | Comment                         |
|--------------|-------|---|---------------------------------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 419483      | WELL | TA     | 05/29/2020  | OW         | 123-32263 | NCLP PC AA04-20 | TA          |

**General Comment:**

This is a WELL / ABANDONED BATTERY inspection.  
Well(s): 1: Temporarily Abandoned | TA.  
Battery: Abandoned. ALL equipment removed.  
Abandoned Battery GPS coord: 40.515875 / -104.447306

Abandoned Centralized Battery formerly served 10 Location IDs  
(419484, 302611, 302612, 302613, 302614, 302615, 302616, 302626, 302627, 302628).  
(Well(s): 10: Temporarily Abandoned | TA).

**Location**

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Lease Road:</b> |          |       |  |
| Type               | Access   |       |  |
| comment:           | Adequate |       |  |
| Corrective Action  |          | Date: |  |

Overall Good: ☐

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | WELLHEAD    |       |  |
| Comment:           | Iron panel. |       |  |
| Corrective Action: |             | Date: |  |

|                               |  |       |                 |
|-------------------------------|--|-------|-----------------|
| <b>Equipment:</b>             |  |       | corrective date |
| Type: Emission Control Device | # 0  |       |                 |
| Comment:                      | Temporarily Abandoned   TA.<br>Battery ABANDONED. ALL Equipment removed. |       |                 |
| Corrective Action:            |  | Date: |                 |
| Type: Bradenhead              | # 1  |       |                 |
| Comment:                      | Appears plumbed to surface.  |       |                 |
| Corrective Action:            |  | Date: |                 |
| Type: Plunger Lift            | # 1  |       |                 |
| Comment:                      |  |       |                 |
| Corrective Action:            |  | Date: |                 |
| Type: Pig Station             | # 0  |       |                 |
| Comment:                      | Temporarily Abandoned   TA.<br>Battery ABANDONED. ALL Equipment removed. |       |                 |
| Corrective Action:            |  | Date: |                 |
| Type: Gas Meter Run           | # 0  |       |                 |
| Comment:                      | Temporarily Abandoned   TA.<br>Battery ABANDONED. ALL Equipment removed. |       |                 |

|                                   |  |       |  |
|-----------------------------------|--|-------|--|
| Corrective Action:                |  | Date: |  |
| Type: Horizontal Heated Separator | # 0  |       |  |
| Comment:                          | Temporarily Abandoned   TA.<br>Battery ABANDONED. ALL Equipment removed. |       |  |
| Corrective Action:                |  | Date: |  |

**Tanks and Berms:**

|                    |  |          |      |         |        |  |
|--------------------|--|----------|------|---------|--------|--|
| Contents           | #  | Capacity | Type | Tank ID | SE GPS |  |
| PRODUCED WATER     | 0  |          |      |         | ,      |  |
| Comment:           | Temporarily Abandoned   TA.<br>Battery ABANDONED. ALL Equipment removed. |          |      |         |        |  |
| Corrective Action: |  |          |      |         | Date:  |  |

**Paint**

|                  |  |  |  |  |  |
|------------------|--|--|--|--|--|
| Condition        |  |  |  |  |  |
| Other (Content)  |  |  |  |  |  |
| Other (Capacity) |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|                    |          |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 419483 Type: WELL API Number: 123-32263 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Battery Abandoned. Disconnected from flowline.  
Locked-Out, Tagged-Out | LOTO.  
Yellow LTSI tag posted.  
COGCC records last production: 03/2017.  
SI/TA well per ALT MIT Assurance program.  
Doc. #02385001. (NOBLE).  
  
Form 4 on file. TA date: 09/28/2018. Approved.  
Form 6A on file. Out-of-Svc Designation. Date: 03/01/2017.  
Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/31/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 09/06/2022 at approximately 13:41 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: NOBLE ENERGY INC<br/> Location Name: NCLP PC /AA04-20<br/> Location ID: 419484<br/> Well Name(s):<br/> NCLP PC AA04-20.<br/> API:<br/> 123-32263.<br/> Location County: Weld County, Colorado<br/> Weather: Mostly Sunny, dry.</p> <p>While there, I observed:<br/> Well(s): 1: Temporarily Abandoned   TA.<br/> Battery: Abandoned. ALL equipment removed.<br/> Abandoned Battery GPS coord: 40.515875 / -104.447306</p> <p>Abandoned Centralized Battery formerly served 10 Location IDs (419484, 302611, 302612, 302613, 302614, 302615, 302616, 302626, 302627, 302628).<br/> (Well(s): 10: Temporarily Abandoned   TA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 09/06/2022 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 707600211    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5849330">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5849330</a> |