

# Inspection Photos

Loc: 325562

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Date: 8/31/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325562 | Date: 8/31/2022

## Inspection Photos



**Photo 1.** Facing northwest toward the location. The well marker is shown at center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325562 | Date: 8/31/2022

## Inspection Photos



**Photo 2.** Facing west at the location. This area east of the well marker has not established sufficient vegetation and should be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325562 | Date: 8/31/2022

## Inspection Photos



**Photo 3.** Facing north on the west side of the PA marker. The vegetation is progressing better west of the well marker.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325562 | Date: 8/31/2022

## Inspection Photos



**Photo 4.** Facing east toward the surrounding undisturbed reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325562 | Date: 8/31/2022