

Inspection Photos

Loc: 325580

Operator: SIMCOE LLC

Inspection Date: 8/31/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325580 | Date: 8/31/2022

Inspection Photos



Photo 1. Facing north along the access road.



Inspection Photos



Photo 2. Northwest side of the location. There has been rock rip/rap installed in the erosion gully that was cited in the previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325580 | Date: 8/31/2022

Inspection Photos



Photo 3. There are wattles and rock rip/rap installed at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 325580 | Date: 8/31/2022