

Inspection Photos

Loc: 334046

Operator: MORNINGSTAR OPERATING LLC

Inspection Date: 8/31/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 334046 | Date: 8/31/2022

Inspection Photos



Photo 1. Facing southeast toward the location.



Inspection Photos



Photo 2. Facing toward the tank battery. There are animal holes in the berm which is compromising the containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 334046 | Date: 8/31/2022

Inspection Photos



Photo 3. Facing northwest at west side of the location. There are some noxious weeds along this area that need to be controlled. (Canada thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 334046 | Date: 8/31/2022