

Inspection Photos

Loc: 312114

Operator: SIMCOE LLC

Inspection Date: 8/31/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 312114 | Date: 8/31/2022

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 312114 | Date: 8/31/2022

Inspection Photos



Photo 2. The fence around the tank battery is in need of maintenance to prevent livestock entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 312114 | Date: 8/31/2022

Inspection Photos



Photo 3. There is an erosion channel at the northeastern area of the location. BMP's need to be installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 312114 | Date: 8/31/2022

Inspection Photos



Photo 4. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 312114 | Date: 8/31/2022