

Inspection Photos  
Location Name: Jack Mleynek #3  
Location ID: 336296



Photo 1 Sep 1 verify well is shut in



Photo 2 loc pic weeds

**Inspection Photos**  
**Location Name: Jack Mleynek #3**  
**Location ID: 336296**



**Photo 3 Weeds around equipment and on location**



**Photo 4 Weeds around electric panel and on location.**