

Inspection Photos
Location Name: Jack A Mileynek #5
Location ID: 332951



Photo 1 Sep 1 inspection to confirm well is shut in



Photo 1 loc pic weeds around equipment and on location

Inspection Photos
Location Name: Jack A Mileynek #5
Location ID: 332951



Photo 3 Well head sign unreadable and weeds around equipment



Photo 4 Access road covered in vegetation (weeds)