

Inspection Photos
Location Name: Jack Mleynek #1
Location ID: 318147



Photo 1 Sep 1 inspection to confirm wells shut in



Photo 1 loc pic

Inspection Photos
Location Name: Jack Mleynek #1
Location ID: 318147



Photo 3 well head



Photo 4 Well head sign faded not legible.