

Inspection Photos
Location Name: Mleynek Jack A #4
Location ID: 318367



Photo 1 Sept 1 inspection to confirm well is shut in



Photo 2 loc pic Weeds on location and around equipment



Inspection Photos
Location Name: Mleynek Jack A #4
Location ID: 318367



Photo 3 sign not legible



Photo 4 weeds on location and around electric panel.

