

Inspection Photos
Location Name: Rogers Unit #2
Location ID:318474



Photo 1 Sept 1 inspection to confirm well is shut in



Photo 2 loc pic

Inspection Photos
Location Name: Rogers Unit #2
Location ID:318474



Photo 3 Well head. Trash (fence in disrepair



Photo 4 Well sign not legible