

Inspection Photos
Location Name: Rodgers #1
Location ID: 336058



Photo 1 Sept 1 inspection to confirm well is shut in



Photo 2 loc pic well sign not legible

Inspection Photos
Location Name: Rodgers #1
Location ID: 336058



Photo 3 loc pic



Photo 4 loc pic