

Inspection Photos
Location Name: Josephine B Miles Unit #3
Location ID: 318612



Photo 1 Sept 1 inspection to confirm well is shut in



Photo 2 loc pic Weeds on location and around equipment



Inspection Photos
Location Name: Josephine B Miles Unit #3
Location ID: 318612



Photo 3 sign faded not legible



Photo 4 weeds on location and around equipment

