

Inspection Photos
Location Name: Josephine B Miles B #1
Location ID: 336326



Photo 1 Sept inspection to confirm well is shut in



Photo 2 loc pic. Weeds on location and around equipment

Inspection Photos
Location Name: Josephine B Miles B #1
Location ID: 336326



Photo 3 sign faded not legible



Photo 4 Weeds on location and around equipment