

Inspection Photos
Location Name: Josephine B Miles #1
Location ID: 317779



Photo 1 Sept 1 inspection to confirm well is shut in



Photo 2 loc pic



Inspection Photos
Location Name: Josephine B Miles #1
Location ID: 317779



Photo 3 well sign faded not legible



Photo 4 stained soil around well head