

Inspection Photos
Location Name: Josephine B Miles #2
Location ID: 318611



Photo 1 sept 1 inspection to confirm well is shut in



Photo 2 loc pic



Inspection Photos
Location Name: Josephine B Miles #2
Location ID: 318611



Photo 3 Weeds around electric equipment



Photo 4 well sign faded and not legible