

# Inspection Photos

Loc: 325776

Operator: SIMCOE LLC

Inspection Date: 8/30/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Loc: 325776 | Date: 8/30/2022

## Inspection Photos



**Photo 1.** Facing southeast toward the location. Well sign posted at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325776 | Date: 8/30/2022

## Inspection Photos



**Photo 2.** Facing toward the pumpjack.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325776 | Date: 8/30/2022



## Inspection Photos



**Photo 3.** Facing toward the southern interim reclamation area which is stabilized with perennial vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 325776 | Date: 8/30/2022