

PETRO MEX RESOURCES – 10059
API# 05-045-06017 COAL GULCH #15-9
Inspection Date : 9/6/2022



Location overview looking S



Wellhead bradenhead valve exposed

PETRO MEX RESOURCES – 10059
API# 05-045-06017 COAL GULCH #15-9
Inspection Date : 9/6/2022



Meter housing and Separator.
Overgrown with weeds.



Produced water tank.
Overgrown with weeds.

PETRO MEX RESOURCES – 10059
API# 05-045-06017 COAL GULCH #15-9
Inspection Date : 9/6/2022



Condensate tank.
Overgrown with weeds.



Overview of equipment.
Overgrown with weeds.