

Final Reclamation Inspection

Date: 09/01/2022

Operator: GRIFFIN MANAGEMENT LLC -100182

Location ID: 378425

Inspection Document #: 696105398

Arapahoe County, CO

SESE Section 16 T4S R61W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KATHY STATE #44-16
Location ID: 378425



Photo 1. Location photo taken from center portion, facing north. Photo illustrates field is fallow with presence of stubble and annual weedy vegetation (e.g. russian thistle).

Inspection Photos
Location Name: KATHY STATE #44-16
Location ID: 378425



Photo 2. Location photo taken from southern edge, facing west. See comments in Photo 1.

Inspection Photos
Location Name: KATHY STATE #44-16
Location ID: 378425



Photo 3. Location photo taken from northern edge, facing south. See comments in photo 1.

Inspection Photos
Location Name: KATHY STATE #44-16
Location ID: 378425



Photo 4. Location photo taken from western edge, facing north. Photo illustrates bare soil possibly a result of compaction (outlined in red).

Inspection Photos
Location Name: KATHY STATE #44-16
Location ID: 378425



Photo 5. Reference photo taken from eastern portion of location, facing east.