

Inspection Photos and Issue Report

8/30/2022

Operator: LARAMIE ENERGY LLC #10433

Location #481742

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #481742



Photo 1: Photos taken from the west end of the current CC 697-15-54 Location #335803 working pad area; construction of the Annex Cuttings Facility Location #481742 will include portions of the CC working pad. Photos 1-2 provide an overview of the Location from north, northeast, southeast, to south. Photos show construction (soil salvage) operations “in-process” at time of inspection.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #481742



September 7, 2022



September 7, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #481742



Photo 3: Photo example showing erosion logs (straw wattles) installed along the eastern perimeter of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #481742



Photo 4: Photo taken from the access road. Photo shows Location entrance for the Annex Cuttings Facility (arrow). Location entrance signage not posted; Form 2A also not posted on Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #481742



Photo 5: Photo taken from the access road. Soil along access road loose/powdery and at risk to wind erosions; application of freshwater to soils not observed; water truck not observed on site or within immediate areas.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location #481742



Photo 6: Photo taken from the turn-off from the main lease road, and the access road leading to the Location. Photo shows controls to minimize tracking and sediment transport was missing or insufficient; sediment transport observed.