

# Inspection Photos

September 6, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313090

Location Name: Warlock State-611N91W /3NWNE

Inspection Document #: 702800661

Moffat County, CO

NWNE Section 3 T11N R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Warlock State-611N91W /3NWNE

Location ID: 313090



**Photo 1.** Photo taken to the west of the Location shows a portion of the access road dominated by annual undesirable plant species (clasping pepperweed, Russian thistle, alyssum) and Noxious Weeds (cheatgrass).



**Photo 2.** Photo taken to the west of the Location shows a portion of the access road where desirable perennial vegetation is well established.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800661

Inspection Photos  
Location Name: Warlock State-611N91W /3NWNE  
Location ID: 313090



**Photo 3.** Photo taken from the northwest shows an overview of the Location. Photo shows areas of the Location with good perennial establishment (green) and poor perennial establishment/high cover of annual weeds including cheatgrass (red).



**Photo 4.** Photo shows the vegetation community on the eastern portion of the Location (see Photo 3 green polygon). Desirable perennial vegetation dominates and additional reclamation is not required in this area.



Inspection Photos  
Location Name: Warlock State-611N91W /3NWNE  
Location ID: 313090



**Photo 5.** Photo shows a close-up of a small patch of Russian knapweed (List B Noxious) at the south of the Location (approximate coordinates: 40.941201, -107.589558).



**Photo 6.** Photo shows an example of hoary tansyaster, a native perennial plant often mistaken for knapweed. Hoary tansyaster is widespread and common on Location, and contributing favorably to desirable cover. This plant should not be mistaken for knapweed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800661

Inspection Photos  
Location Name: Warlock State-611N91W /3NWNE  
Location ID: 313090



**Photo 7.** Photo taken from the west of the Location shows a patch of whitetop (List B Noxious) which has gone to seed.



**Photo 8.** Photo taken from the east of the Location shows a straw wattle installed along the downslope perimeter of the Location. This wattle must be removed and long term stabilization must be achieved before the site can receive a passing final reclamation inspection.



Inspection Photos  
Location Name: Warlock State-611N91W /3NWNE  
Location ID: 313090



**Photo 9.** Photo shows an example of trash/debris which is scattered throughout the Location.



**Photo 10.** Photo shows an example of trash/debris which is scattered throughout the Location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800661

Inspection Photos

Location Name: Warlock State-611N91W /3NWNE

Location ID: 313090



**Photo 11.** Photo taken from the northwest of the Location shows the start of the disturbed area vegetation monitoring transect.



**Photo 12.** Photo taken from the northwest of the Location shows the ground surface at the start of the disturbed area vegetation monitoring transect.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800661

Inspection Photos

Location Name: Warlock State-611N91W /3NWNE

Location ID: 313090



**Photo 13.** Photo taken from the west of the Location shows the end of the disturbed area vegetation monitoring transect.



**Photo 14.** Photo taken from the west of the Location shows the ground surface at the end of the disturbed area vegetation monitoring transect.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800661

Inspection Photos

Location Name: Warlock State-611N91W /3NWNE

Location ID: 313090



**Photo 15.** Photo taken to the west of the Location shows the start of the reference area vegetation monitoring transect.



**Photo 16.** Photo taken to the west of the Location shows the ground surface at the start of the reference area vegetation monitoring transect.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800661

Inspection Photos

Location Name: Warlock State-611N91W /3NWNE

Location ID: 313090



**Photo 17.** Photo taken to the west of the Location shows the end of the reference area vegetation monitoring transect.



**Photo 18.** Photo taken to the west of the Location shows the ground surface at the end of the reference area vegetation monitoring transect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800661