

# Inspection Photos

September 6, 2022

Operator: True Oil LLC - #90450

Location ID: 313091

Location Name: Peak State-611N91W /10NWNW

Inspection Document #: 702800666

Moffat County, CO

NWNW Section 10 T11N R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Peak State-611N91W /10NWNW

Location ID: 313091



**Photo 1.** Photo taken to the east of the Location shows the access road. Perennial grasses are sparse, while Russian thistle, an undesirable plant species/annual weed is common. Cheatgrass is also present.



**Photo 2.** Photo shows a close-up of the vegetation on the access road. Perennial grasses are sparse. Russian thistle, an undesirable plant species/annual weed is the greener plant in the photo.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800666

## Inspection Photos

Location Name: Peak State-611N91W /10NWNW

Location ID: 313091



**Photo 3.** Photo taken from the north shows an overview of the Location.



**Photo 4.** Photo shows an example of areas of the Location where bare ground dominates. The darker green vegetation in the photo is tumbling saltweed and Russian thistle (annual/undesirable).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800666

## Inspection Photos

Location Name: Peak State-611N91W /10NWNW

Location ID: 313091



**Photo 5.** Photo shows an example of bull thistle, a List B Noxious weed occasionally found on Location. The plant has gone to seed.



**Photo 6.** Photo shows a patch of tumbling saltweed and Russian thistle (annual/undesirable).



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800666

## Inspection Photos

Location Name: Peak State-611N91W /10NWNW

Location ID: 313091



**Photo 7.** Photo shows an overview of the vegetation community on Location.



**Photo 8.** Photo taken from the north of the Location shows the transition between the disturbed Location (left) and undisturbed reference area (right). Note, the darker green vegetation on Location is Russian thistle (annual/undesirable).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800666


Inspection Photos

Location Name: Peak State-611N91W /10NWNW

Location ID: 313091



**Photo 9.** Photo taken to the south of the Location shows the reference area vegetation community.



**Photo 10.** Photo taken to the north of the Location shows the reference area vegetation community.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800666