


**Inspection Photos**  
**Location Name: Thomas Jacquez E 1**  
**Location ID: 326167**



**IMG 01**  
**Well sign**



**IMG 02**  
**Location overview**





**IMG 03**

**Weeds near produced water tank**



**IMG 04**

**Weeds near compressor**





**IMG 05**  
**Stairs**



**IMG 06**  
**Unused supplies/debris**





**IMG 07**  
**Unused equipment**



**IMG 08**  
**Unused equipment**





IMG 09

Unused equipment



IMG 10

Spill prevention