

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/08/2022

Submitted Date:

09/09/2022

Document Number:

702500411

FIELD INSPECTION FORM

 Loc ID 312122 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num:
Operator Information:
 OGCC Operator Number: 7650
 Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
 Address: 4900 COLLEGE BLVD
 City: FARMINGTON State: NM Zip: 87402
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214684	WELL	PR	10/01/2020	GW	067-06288	FLUME CANYON 4	WK

General Comment:

Inspector Alex Klink on site at 09:15 AM on 9/8/2020 to observe and witness plugging operations.

At 09:15 AM current operations are WOC. 16 sacks of class G cement with 2% calcium were pumped earlier that morning over interval 4450'-4248'. Tag plug #1 at 4285'. Pressue test at 500 PSI, test failed, dropped 100 PSI in 1 minute. Pump plug #2 28 sacks from 3250'-3239'.

Inspected Facilities

Facility ID: 214684 Type: WELL API Number: 067-06288 Status: PR Insp. Status: WK

Cement

Cement Contractor

Contractor Name: A+ Well Service

Contractor Phone: (505) 325-2627

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: At 09:15 AM current operations are WOC. 16 sacks of class G cement with 2% calcium were pumped earlier that morning over interval 4450'-4248'. Tag plug #1 at 4285'. Pressue test at 500 PSI, test failed, dropped 100 PSI in 1 minute. Pump plug #2 28 sacks from 3250'-3239'.

Corrective Action: _____

Date: _____