

Inspection Photos

API: 071-07991

Operator: OGRIS OPERATING LLC

Inspection Date: 9/8/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 9/8/2022

Inspection Photos



Photo 1. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 9/8/2022

Inspection Photos



Photo 2. Stained soils near the engine skid have been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 9/8/2022