

Inspection Photos

API: 071-09478

Operator: OGRIS OPERATING LLC

Inspection Date: 9/8/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09478 | Date: 9/8/2022

Inspection Photos



Photo 1. Facing south toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09478 | Date: 9/8/2022

Inspection Photos



Photo 2. There is some insulation debris at the north side of the location that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09478 | Date: 9/8/2022

Inspection Photos



Photo 3. Leak has been repaired.

