

# Inspection Photos

API: 071-09487

Operator: OGRIS OPERATING LLC

Inspection Date: 9/8/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09487 | Date: 9/8/2022

## Inspection Photos



**Photo 1.** Facing southeast toward the well site.



## Inspection Photos



**Photo 2.** Facing toward the west fill slope at the location. The vegetation appears to be stabilizing this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09487 | Date: 9/8/2022

## Inspection Photos



**Photo 3.** Sign installed at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09487 | Date: 9/8/2022