

# Inspection Photos and Issue Report

9/7/2022

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #324411

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #324411



**Photo 1:** Photos taken from the southwest of the working pad. Photos 1-2 provide an overview of the production areas from northwest, north, east to southeast.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #324411



September 7, 2022



September 7, 2022

**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #324411



September 7, 2022

**Photo 3:** Single active well on Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #324411



September 7, 2022



September 7, 2022

**Photo 2:** Photos example of interim areas on the west end of the Location. Photos example or areas progressing towards 1003 standards.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #324411



September 7, 2022



September 7, 2022

**Photo 5:** Photos examples showing interim areas of the Location where desirable perennial plant germination and establishment is sparse. Additional reclamation efforts will likely be required in these areas.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #324411



**Photo 6:** Photo taken from the northern interim areas of the Location. Photo shows Houndstongue rosettes established on the Location.